



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 6

1445 ROSS AVENUE, SUITE 1200
DALLAS, TX 75202-2733

August 31, 2015

Mr. Robert Brooks,
State Archaeologist
Oklahoma Archeological Survey
111 East Chesapeake, No. 102
Norman, Oklahoma 73019-5111

RE: Wilcox Oil Company Superfund Site and National Historic Preservation Act Section 106

Dear Mr. Brooks:

The Wilcox Oil Company Superfund Site (Site) in Bristow, Creek County, Oklahoma was listed on the National Priorities List in December 2013 under the Comprehensive, Environmental, Response, Compensation, and Liability Act (CERCLA), commonly known as Superfund. Because this Site is listed, the United States Environmental Protection Agency (EPA) and Oklahoma Department of Environmental Quality (ODEQ) will be investigating the Site to determine the nature and extent of hazardous substances, pollutants, or contaminants as well as the human health and environmental risks that may be present as a result of former operations. Future actions at the Site may include remediation of contamination based on the results of the investigation and associated risk assessments.

This project is subject to review under Section 106 of the National Historic Preservation Act of 1966, as amended. Based on our review of the National Register of Historic Places, the history of operation, and investigations performed by ODEQ, no State cultural or historical resources or properties are located within the project boundary or will be affected by the investigation and potential remediation that will be conducted by EPA and the ODEQ.

Please find provided on the following pages, Site information to assist with your review. Documentation as detailed in Section 800.11(d) includes,

- a description of the Wilcox Oil Company Superfund Site;
- a delineation of the area of potential effects, including maps, aerial photographs, and Site photographs;
- a summary description of the effort we made to identify historic properties; and,
- the basis for determining that no historic properties are present or affected.

Due to the nature of the activities at the Site and the long-term operation of the refinery (approximately 40 to 50 years), this Site is both heavily contaminated and disturbed. Thus, there are no historic properties present which leads us to a no adverse effect determination for this Site.

Please review the material enclosed and contact me at (214) 665-8143, or coltrain.katrina@epa.gov if you have questions. If we do not hear from you within 30 days after your receipt of this letter, we will assume that you do not object to our determination of no adverse effect to historic properties. EPA will proceed with the Site investigation and remediation and will notify you as well as the Oklahoma State Historic Preservation Officer regarding any inadvertent discovery of historic properties.

Sincerely,

A handwritten signature in black ink, appearing to read 'K. Coltrain', with a large, stylized loop at the end.

Katrina Higgins-Coltrain
Remedial Project Manager
LA/OK/NM Section, Superfund Division

State Archaeologist Concurs with Finding: _____

State Archaeologist Review and Date: _____

Enclosure 1: Site Description and Operation History

Full Title of Site: Wilcox Oil Company Superfund Site (OK0001010917)

Federal Funding Agency: The funding agency requesting the historical review is the United States Environmental Protection Agency, Region 6.

Wilcox Oil Company Location: Reference Maps included.

Address: West 221st Street South/Refinery Road, 0.35 mile east of U.S. Highway 66

City, County, State: Bristow, Creek County, OK, 74010

Topographic Map: Bristow Quadrangle, OK

Latitude: 35°50'26.8966" N Longitude: 96°22'48.693" W

Township-Range: N ½ of the NW ¼ of S29 T16N R9E and the SW ¼ of the SW ¼ of S20 T16N R9E

Site History and Background: The Wilcox Oil Company Superfund Site (Site) is an abandoned and demolished oil refinery and associated tank farm located north of Bristow, Creek County, Oklahoma. The geographic coordinates of the Site are approximately 35°50'31" North latitude and 96°23'02" West longitude. A detailed title search in the Creek County Clerk office confirms that the property was used in oil refinery operations from approximately 1915 until November 1963. The former Lorraine refinery, including associated tank farm, covers approximately 20 of the 125 acre Site, and operated under numerous companies from approximately 1915 to 1937 when the property was sold to Wilcox Oil and Gas Company. Wilcox Oil and Gas Company purchased refinery operations on the remaining acres east of the railroad tracks and operated as a crude oil refinery from the 1920s until the property was sold on 1 November 1963.

A modern skimming and cracking plant was constructed in 1929. The upgraded facility had an operating capacity of 4,000 barrels of crude oil per day. The main components of the system consisted of a skimming plant, cracking unit, and redistillation battery with a vapor recovery system and continuous treating equipment. The crude oil was brought directly from the field, eliminating storage and handling facilities, but resulting in crude with high sediment and water.

Sanborn fire insurance maps can be used to understand historical property usage. The Wilcox Oil and Gas Company and Lorraine Refining Company Sanborn Insurance Maps indicate that the properties contained approximately 80 storage tanks of various sizes, a cooling pond, and around 10 buildings housing refinery operations. The maps also indicate that crude oil, fuel oil, gas oil, distillate, kerosene, naphtha, and benzene (petroleum ether) were all stored on the property.

The Site can be divided into four major former operational areas: the Wilcox refinery, the Lorraine refinery, the north tank farm, and the east tank farm.

- The former Wilcox refinery area is fenced and covers approximately 26 acres. Most of the equipment and storage tanks that remained on-site in 1963 were auctioned and have been salvaged for scrap iron by private land owners, and what remains are in ruins. Four aboveground storage tanks (12,500 gallons each) remain standing, in addition to a number of buildings, discarded drums and pieces of scrap iron and piping. There are multiple areas of stressed vegetation, barren areas, and visible black tarry waste of a

hydrocarbon nature. A building in the northern part of the former refinery has been converted to a residence. An intermittent creek flows southward across the eastern portion of the refinery area through a small pond in the southeast corner of the refinery area and into Sand Creek.

- The former Lorraine refinery area covers approximately 8 acres and includes the southwestern portion of the Site, south of Refinery Road and west of the railroad. No refinery structures remain in the processing area. The First Assembly of God Church, a playground, and one residence are located here. There are multiple areas of stressed vegetation, barren areas, and visible black tarry waste of a hydrocarbon nature.
- The East tank farm was a large crude oil storage area/tank farm covering approximately 79 acres and contains pits, ponds, and a number of circular berms that surrounded tank locations. All of the tanks have been cut down and removed; however, remnants of the tank locations remain and are visible. Many of the berms surrounding the pits, ponds, and former tanks have been cut or leveled. An intermittent creek is located in the eastern portion of the tank farm and flows south to Sand Creek. A pumping or gas compressor station exists in the north-central portion of the Site, and an active pipeline crosses from northwest to southeast across the middle of the Site. There are four residences located on top of or directly next to former tank locations. There are multiple areas of stressed vegetation, barren areas, and visible black tarry waste of a hydrocarbon nature. Waste was also observed in several drainage channels that empty into Sand Creek.
- The North tank farm was a crude and fuel oil storage area consisting of approximately 12 acres. No refinery structures remain in the product storage area, and all tanks have been cut down and removed. Remnants of the tank locations are not visible, and historic locations are difficult to pinpoint. One residence is located in this area.

After the refinery operations ceased and most of the tanks and buildings demolished and sold for scrap, the property was sold to private interests. Beginning in 1975 with the construction of the church, private residences were constructed on 6 parcels of land that were part of the former refinery operations. The most recent being constructed in 2003/2004. One former building associated with the refinery was repurposed as a residence. As a result, there are a total of seven residences on the Site, all of which are located on former tank or refinery operations locations. Three of the residences located on the eastern portion of the Site are known to use water from domestic/private wells. The drainage pattern of the Site is primarily towards Sand Creek which provides the western and southwestern boundaries of the Site. Two intermittent streams and several drainage channels cross the portion of the Site east of the railroad and flow into Sand Creek.

The refinery waste source areas of concern include a backfilled oily waste pond and pit, a breached settling pond, a former pond apparently backfilled with solid refinery waste, and a number of former tank storage areas. The contaminants of concern are metals and organic compounds (Total Petroleum Hydrocarbons (TPH) and Polycyclic Aromatic Hydrocarbons (PAHs)). These potential contaminants of concern are found in soil, sediment, and waste material.

Investigation History: Multiple investigations have been performed on the Site since 1994. These documents were used to summarize the Site background and operational history described above.

- Preliminary Assessment (PA) was performed at the former Wilcox Refinery Site by the Oklahoma Department of Environmental Quality (ODEQ) in December 1994.
- Expand Site Inspection (ESI) was performed at the former Wilcox Refinery Site for the Environmental Protection Agency (EPA) in March 1997.
- Site Assessment (SA) was performed at the former Wilcox Refinery Site by EPA in March 1999.
- PA was performed at the former Lorraine Refinery Site by ODEQ in September 2008.
- Site Inspection (SI) was performed at the former Lorraine Refinery Site by ODEQ in August 2009.
- ESI was performed at the former Lorraine Refinery Site by ODEQ in September 2010.
- ESI was performed at the former Wilcox Refinery Site by ODEQ in September 2011.
- Hazard Ranking System Package completed in May 2013.
- Residential Sampling completed 2015. Data review is underway.
- 2015: Planned and ongoing RI investigation by EPA including geophysical and direct sensing techniques.

Cleanup History: The following actions have been taken at the Site.


- EPA and ODEQ met with residents on March 24 and 25, 2015, to talk about property sampling. As a result, the EPA sampled 9 residential properties in May/June 2015 and fenced additional areas of concern.
- In November 2014, ODEQ informed EPA that there was a potential elevated level of lead in the blood of a child living on the Site. The EPA developed a sampling plan and sampled the property in December 2014.
- In July 2014, the EPA installed a cap on the drinking water well near the Church on the Site and put up a fence with signs around an area of concern.
- Currently, ODEQ is performing quarterly testing of drinking water wells for residents in and around this Site. No Maximum Contaminant Levels (MCLs) have been exceeded.

Cleanup Status: This Site is currently in the Remedial Investigation and Feasibility Study phase of the Superfund process. The RI/FS identifies the type and extent of contamination, evaluates if there is a health risk for humans and wildlife, identifies a list of cleanup options that can be used to cleanup the contamination at the Site, and estimates the cost of each cleanup option. Based on results of the RI/FS phase, a Proposed Plan is written to identify the preferred cleanup option and the cost. The Proposed Plan is expected to be released to the public for review and comment in 2018.

Enclosure 2: Delineation of the area of potential effects, including maps, aerial photographs, and Site photographs

Enclosure 2a: Delineation of the area of potential effects

Wilcox Oil Company Superfund Site Bristow, OK



North Tank Farm

Loading Dock

Lorraine
process area

Wilcox process
area

East Tank Farm


Site in Sec 20&29-16N-9E
Creek County
1"= 660' 8/19/1941

0 330 660 Feet
August 21, 2015

Wilcox Oil Company Superfund Site and National Historic Preservation Act Section 106
Boundaries are approximate.

Page 9 of 62

Wilcox Oil Company 2014 Aerial Photograph



North Tank Farm

Loading Dock

Lorraine
process
area

Wilcox process
area

East Tank Farm

Google Earth

Wilcox Oil Company Superfund Site and National Historic Preservation Act Section 106
August 31, 2015

Boundaries are approximate.

Page 10 of 62
1000 ft



Residence

Wilcox/Lorraine Refinery

Refinery Rd

Bristow, OK 74010

Inquiry Number: 3313889.1

May 01, 2012

Certified Sanborn® Map Report



Certified Sanborn® Map Report

5/01/12

Site Name:

Wilcox/Lorraine Refinery
Refinery Rd
Bristow, OK 74010

Client Name:

Dynamac Corporation
1202 Executive Drive West
Richardson, TX 75081

EDR Inquiry # 3313889.1

Contact: Kris Lloyd



The complete Sanborn Library collection has been searched by EDR, and fire insurance maps covering the target property location provided by Dynamac Corporation were identified for the years listed below. The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by Sanborn Library LLC, the copyright holder for the collection.

Certified Sanborn Results:

Site Name: Wilcox/Lorraine Refinery
Address: Refinery Rd
City, State, Zip: Bristow, OK 74010
Cross Street:
P.O. # NA
Project: S109-20F
Certification # 398F-439D-A25F



Sanborn® Library search results
Certification # 398F-439D-A25F

Maps Provided:

1961
1923
1920
1915

The Sanborn Library includes more than 1.2 million Sanborn fire insurance maps, which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☒ Library of Congress
- ☒ University Publications of America
- ☒ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Dynamac Corporation (the client) is permitted to make up to THREE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.


Disclaimer - Copyright and Trademark notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2012 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

1961 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

398F-439D-A25F
Certification #



1923 Certified Sanborn Map



398F-439D-A25F

Certification #


Wilcox Oil Company Superfund Site and National Historic Preservation Act Section 106
August 31, 2015

Scale 100 Ft. to One In
100

Site Name: Wilcox/Lorraine Refinery
Address: Refinery Rd
City, ST, ZIP: Bristow OK 74010
Client: Dynamac Corporation
EDR Inquiry: 3313889.1
Order Date: 5/1/2012 4:35:02 PM
Certification # 398F-439D-A25F
Copyright: 1923



1920 Certified Sanborn Map



WATER FACILITIES

Continued gravity and direct pressure system of water works. Supply from 8 deep wells. One 8" well 250 deep. One 6" well 150 deep. One 4" well 100 deep. One 3" well 50 deep. One 2" well 25 deep. One 1" well 12 deep. One 1/2" well 6 deep. One 1/4" well 3 deep. One 1/8" well 1 1/2 deep. One 1/16" well 3/4 deep. One 1/32" well 3/8 deep. One 1/64" well 3/16 deep. One 1/128" well 3/32 deep. One 1/256" well 3/64 deep. One 1/512" well 3/128 deep. One 1/1024" well 3/256 deep. One 1/2048" well 3/512 deep. One 1/4096" well 3/1024 deep. One 1/8192" well 3/2048 deep. One 1/16384" well 3/4096 deep. One 1/32768" well 3/8192 deep. One 1/65536" well 3/16384 deep. One 1/131072" well 3/32768 deep. One 1/262144" well 3/65536 deep. One 1/524288" well 3/131072 deep. One 1/1048576" well 3/262144 deep. One 1/2097152" well 3/524288 deep. One 1/4194304" well 3/1048576 deep. One 1/8388608" well 3/2097152 deep. One 1/16777216" well 3/4194304 deep. One 1/33554432" well 3/8388608 deep. One 1/67108864" well 3/16777216 deep. One 1/134217728" well 3/33554432 deep. One 1/268435456" well 3/67108864 deep. One 1/536870912" well 3/134217728 deep. One 1/1073741824" well 3/268435456 deep. One 1/2147483648" well 3/536870912 deep. One 1/4294967296" well 3/1073741824 deep. One 1/8589934592" well 3/2147483648 deep. One 1/17179869184" well 3/4294967296 deep. One 1/34359738368" well 3/8589934592 deep. One 1/68719476736" well 3/17179869184 deep. One 1/137438953472" well 3/34359738368 deep. One 1/274877907344" well 3/68719476736 deep. One 1/549755814688" well 3/137438953472 deep. One 1/1099511629376" well 3/274877907344 deep. One 1/2199023258752" well 3/549755814688 deep. One 1/4398046517504" well 3/1099511629376 deep. One 1/8796093035008" well 3/2199023258752 deep. One 1/17592186070016" well 3/4398046517504 deep. One 1/35184372140032" well 3/8796093035008 deep. One 1/70368744280064" well 3/17592186070016 deep. One 1/140737488560128" well 3/35184372140032 deep. One 1/281474977120256" well 3/70368744280064 deep. One 1/562949954240512" well 3/140737488560128 deep. One 1/1125899908481024" well 3/281474977120256 deep. One 1/2251799816962048" well 3/562949954240512 deep. One 1/4503599633924096" well 3/1125899908481024 deep. One 1/9007199267848192" well 3/2251799816962048 deep. One 1/18014398537696384" well 3/4503599633924096 deep. One 1/36028797075392768" well 3/9007199267848192 deep. One 1/72057594150785536" well 3/18014398537696384 deep. One 1/144115188301571072" well 3/36028797075392768 deep. One 1/288230376603142144" well 3/72057594150785536 deep. One 1/576460753206284288" well 3/144115188301571072 deep. One 1/1152921506412568576" well 3/288230376603142144 deep. One 1/2305843012825137152" well 3/576460753206284288 deep. One 1/4611686025650274304" well 3/1152921506412568576 deep. One 1/9223372051300548608" well 3/2305843012825137152 deep. One 1/18446744102601097216" well 3/4611686025650274304 deep. One 1/36893488205202194432" well 3/9223372051300548608 deep. One 1/73786976410404388864" well 3/18446744102601097216 deep. One 1/147573952816808777728" well 3/36893488205202194432 deep. One 1/295147905633617555456" well 3/73786976410404388864 deep. One 1/590295811267235110912" well 3/147573952816808777728 deep. One 1/1180591622534470221824" well 3/295147905633617555456 deep. One 1/2361183245068940443648" well 3/590295811267235110912 deep. One 1/4722366490137880887296" well 3/1180591622534470221824 deep. One 1/9444732980275761774592" well 3/2361183245068940443648 deep. One 1/18889465960551523549184" well 3/4722366490137880887296 deep. One 1/37778931921103047098368" well 3/9444732980275761774592 deep. One 1/75557863842206094196736" well 3/18889465960551523549184 deep. One 1/151115727684412188393472" well 3/37778931921103047098368 deep. One 1/302231455368824376786944" well 3/75557863842206094196736 deep. One 1/604462910737648753573888" well 3/151115727684412188393472 deep. One 1/1208925821475297507147776" well 3/302231455368824376786944 deep. One 1/2417851642950595014295552" well 3/604462910737648753573888 deep. One 1/4835703285901190028591104" well 3/1208925821475297507147776 deep. One 1/9671406571802380057182208" well 3/2417851642950595014295552 deep. One 1/19342813143604760114364416" well 3/4835703285901190028591104 deep. One 1/38685626287209520228728832" well 3/9671406571802380057182208 deep. One 1/77371252574419040457457664" well 3/19342813143604760114364416 deep. One 1/154742505148838080914915328" well 3/38685626287209520228728832 deep. One 1/309485010297676161829830656" well 3/77371252574419040457457664 deep. One 1/618970020595352323659661312" well 3/154742505148838080914915328 deep. One 1/1237940041190704647319322624" well 3/309485010297676161829830656 deep. One 1/2475880082381409294638645248" well 3/618970020595352323659661312 deep. One 1/4951760164762818589277290496" well 3/1237940041190704647319322624 deep. One 1/9903520329525637178554580992" well 3/2475880082381409294638645248 deep. One 1/19807040659051274357109161888" well 3/4951760164762818589277290496 deep. One 1/39614081318102548714218323776" well 3/9903520329525637178554580992 deep. One 1/79228162636205097428436647552" well 3/19807040659051274357109161888 deep. One 1/158456325272410194856873295104" well 3/39614081318102548714218323776 deep. One 1/316912650544820389713746590208" well 3/79228162636205097428436647552 deep. One 1/633825301089640779427493180416" well 3/158456325272410194856873295104 deep. One 1/1267650602179281558854986360832" well 3/316912650544820389713746590208 deep. One 1/2535301204358563117709972721664" well 3/633825301089640779427493180416 deep. One 1/5070602408717126235419945443328" well 3/1267650602179281558854986360832 deep. One 1/10141204817434252470839890886656" well 3/2535301204358563117709972721664 deep. One 1/20282409634868504941679781773312" well 3/5070602408717126235419945443328 deep. One 1/40564819269737009883359563546624" well 3/10141204817434252470839890886656 deep. One 1/81129638539474019766719127093248" well 3/20282409634868504941679781773312 deep. One 1/16225927707894803953343825418688" well 3/40564819269737009883359563546624 deep. One 1/32451855415789607906687650837376" well 3/81129638539474019766719127093248 deep. One 1/64903710831579215813375301674752" well 3/16225927707894803953343825418688 deep. One 1/129807421663158431626750603349504" well 3/32451855415789607906687650837376 deep. One 1/259614843326316863253501206699008" well 3/64903710831579215813375301674752 deep. One 1/519229686652633726507002413398016" well 3/129807421663158431626750603349504 deep. One 1/1038459373305267453014004826796032" well 3/259614843326316863253501206699008 deep. One 1/2076918746610534906028009653592064" well 3/519229686652633726507002413398016 deep. One 1/4153837493221069812056019307184128" well 3/1038459373305267453014004826796032 deep. One 1/8307674986442139624112038614368256" well 3/2076918746610534906028009653592064 deep. One 1/16615349968884279248224077228736512" well 3/4153837493221069812056019307184128 deep. One 1/33230699937768558496448154457473024" well 3/8307674986442139624112038614368256 deep. One 1/66461399875537116992896308914946048" well 3/16615349968884279248224077228736512 deep. One 1/132922799751074233985792617829932096" well 3/33230699937768558496448154457473024 deep. One 1/265845599502148467971585235659864192" well 3/66461399875537116992896308914946048 deep. One 1/531691199004296935943170471319728384" well 3/132922799751074233985792617829932096 deep. One 1/1063382398008593871886340942639456768" well 3/265845599502148467971585235659864192 deep. One 1/2126764796017187743772681885278913536" well 3/531691199004296935943170471319728384 deep. One 1/4253529592034375487545363770557827072" well 3/1063382398008593871886340942639456768 deep. One 1/8507059184068750975090727541115654144" well 3/2126764796017187743772681885278913536 deep. One 1/17014118368137501950181455082231308288" well 3/4253529592034375487545363770557827072 deep. One 1/34028236736275003900362910164462616576" well 3/8507059184068750975090727541115654144 deep. One 1/68056473472550007800725820328925233152" well 3/17014118368137501950181455082231308288 deep. One 1/136112946945100015601457640657850466304" well 3/34028236736275003900362910164462616576 deep. One 1/272225893890200031202915281315700932608" well 3/68056473472550007800725820328925233152 deep. One 1/544451787780400062405830562631401865216" well 3/136112946945100015601457640657850466304 deep. One 1/1088903575760800124811661125262803730432" well 3/272225893890200031202915281315700932608 deep. One 1/2177807151521600249623322250525607460864" well 3/544451787780400062405830562631401865216 deep. One 1/4355614303043200499246644501051214921728" well 3/1088903575760800124811661125262803730432 deep. One 1/8711228606086400998493289002102429843456" well 3/2177807151521600249623322250525607460864 deep. One 1/17422457212172801996986578004204859686912" well 3/4355614303043200499246644501051214921728 deep. One 1/34844914424345639937973156008409719373824" well 3/8711228606086400998493289002102429843456 deep. One 1/69689828848691279875946312016819438747648" well 3/17422457212172801996986578004204859686912 deep. One 1/139379657697382559751892624033638877495296" well 3/34844914424345639937973156008409719373824 deep. One 1/278759315394765119503785248067277754990592" well 3/69689828848691279875946312016819438747648 deep. One 1/557518630789530239007570496134555509981184" well 3/139379657697382559751892624033638877495296 deep. One 1/1115037261579060478015140992269111019962368" well 3/278759315394765119503785248067277754990592 deep. One 1/2230074523158120956030281984538222039924736" well 3/557518630789530239007570496134555509981184 deep. One 1/4460149046316241912060563969076444079849472" well 3/1115037261579060478015140992269111019962368 deep. One 1/8920298092632483824121127938152888159898944" well 3/2230074523158120956030281984538222039924736 deep. One 1/17840596185264967648242254876305776397997888" well 3/4460149046316241912060563969076444079849472 deep. One 1/35681192370529935296484509752611552795995776" well 3/8920298092632483824121127938152888159898944 deep. One 1/71362384741059870592969019505223105591991552" well 3/17840596185264967648242254876305776397997888 deep. One 1/142724769482119741185937839010446211183983104" well 3/35681192370529935296484509752611552795995776 deep. One 1/285449538964239482371875678020892423767966208" well 3/71362384741059870592969019505223105591991552 deep. One 1/570899077928478964743751356041784847535932416" well 3/142724769482119741185937839010446211183983104 deep. One 1/1141798155856957929487502712083689695071868832" well 3/285449538964239482371875678020892423767966208 deep. One 1/2283596311713915858975005424167379390143737664" well 3/570899077928478964743751356041784847535932416 deep. One 1/4567192623427831717950010848334758780287475328" well 3/1141798155856957929487502712083689695071868832 deep. One 1/9134385246855663435900021696669517560574950656" well 3/2283596311713915858975005424167379390143737664 deep. One 1/18268770493711326871800043933339035121149901312" well 3/4567192623427831717950010848334758780287475328 deep. One 1/36537540987422653743600087866678070242299802624" well 3/9134385246855663435900021696669517560574950656 deep. One 1/73075081974845307487200175733356140484599605248" well 3/18268770493711326871800043933339035121149901312 deep. One 1/146150163949690614974400351466712280969199204496" well 3/36537540987422653743600087866678070242299802624 deep. One 1/292300327899381229948800702933424561938398408992" well 3/73075081974845307487200175733356140484599605248 deep. One 1/584600655798762459897601405866849123876796817984" well 3/146150163949690614974400351466712280969199204496 deep. One 1/1169201311597524919795202817337698247753593635968" well 3/292300327899381229948800702933424561938398408992 deep. One 1/2338402623195049839590405634675396495507187271936" well 3/584600655798762459897601405866849123876796817984 deep. One 1/4676805246390099679180811269350792991014374543872" well 3/1169201311597524919795202817337698247753593635968 deep. One 1/9353610492780199358361622538701585982028749087744" well 3/2338402623195049839590405634675396495507187271936 deep. One 1/18707220985560398716723245077403171964057498175488" well 3/4676805246390099679180811269350792991014374543872 deep. One 1/37414441971120797433446490154806343928114996350976" well 3/9353610492780199358361622538701585982028749087744 deep. One 1/74828883942241594866892980309612687856229992701952" well 3/18707220985560398716723245077403171964057498175488 deep. One 1/149657767884433189733785960619225375712459854403904" well 3/37414441971120797433446490154806343928114996350976 deep. One 1/299315535768866379467571921238450751424919708807808" well 3/74828883942241594866892980309612687856229992701952 deep. One 1/598631071537732758935143842476901502849839417615616" well 3/149657767884433189733785960619225375712459854403904 deep. One 1/119726214307546551787028768495380300569967823231232" well 3/299315535768866379467571921238450751424919708807808 deep. One 1/239452428615093103574057536990760601139935646462464" well 3/598631071537732758935143842476901502849839417615616 deep. One 1/478904857230186207148115173981521202279871292924928" well 3/119726214307546551787028768495380300569967823231232 deep. One 1/957809714460372414296230347963042404559742585849856" well 3/239452428615093103574057536990760601139935646462464 deep. One 1/191561942892074428859246069592608480911948111769912" well 3/478904857230186207148115173981521202279871292924928 deep. One 1/383123885784148857718492139185216961823896223539824" well 3/957809714460372414296230347963042404559742585849856 deep. One 1/766247771568297715436984278370433923647792447079648" well 3/191561942892074428859246069592608480911948111769912 deep. One 1/1532495543136595430873968556740867847295584894153296" well 3/383123885784148857718492139185216961823896223539824 deep. One 1/3064991086273190861747937113481735694591169788306592" well 3/766247771568297715436984278370433923647792447079648 deep. One 1/6129982172546381723495874226963471389182339576613184" well 3/1532495543136595430873968556740867847295584894153296 deep. One 1/1225996434509276344699174845392694277836467915322688" well 3/3064991086273190861747937113481735694591169788306592 deep. One 1/2451992869018552689398349

1915 Certified Sanborn Map



RUNS DAY & NIGHT - 1 NIGHT BURNHAM-POWER-STEAM
WERT-STORE IN OFF-POLAND, LIGHTS: GAS FURNACE
IN TOWN NO. WELL WATER-STEAM PIPE TO TANK NO.
WITH SPRAY IN EACH TANK-

Located 1 Mile N. of P.O.
Es. Treasure Box Site


[illegible]

FIRE DEPT:
Volunteer Co. of 13 Men, 2 Hose Carts, 2200' 2 1/2" C.R. hose
in good condition.
Fire alarm: members of Fire Dept called by telephone.
Grades: level. Streets: not paved. Public lights: electric.



STREETS		S		S	
Chatham	11	Second Ave.	11	Primary Center Bldg.	11
English Ave.	11	Third Ave.	11	7th Marine Barracks	11
English Ave.	11	Fourth Ave.	11	High School	11
English Ave.	11	Fifth Ave.	11	Infantry Building	11
English Ave.	11	Sixth Ave.	11	Jail	11
English Ave.	11	Seventh Ave.	11	Kilo-Lowrance Lumber Co.	11
English Ave.	11	Eighth Ave.	11	Laurel Bldg.	11
English Ave.	11	Ninth Ave.	11	Mail Station	11
English Ave.	11	Tenth Ave.	11	Marine Barracks	11
English Ave.	11	Eleventh Ave.	11	Naval Station	11
English Ave.	11	Twelfth Ave.	11	Naval Station	11
English Ave.	11	Thirteenth Ave.	11	Naval Station	11
English Ave.	11	Fourteenth Ave.	11	Naval Station	11
English Ave.	11	Fifteenth Ave.	11	Naval Station	11
English Ave.	11	Sixteenth Ave.	11	Naval Station	11
English Ave.	11	Seventeenth Ave.	11	Naval Station	11
English Ave.	11	Eighteenth Ave.	11	Naval Station	11
English Ave.	11	Nineteenth Ave.	11	Naval Station	11
English Ave.	11	Twentieth Ave.	11	Naval Station	11
English Ave.	11	Twenty-first Ave.	11	Naval Station	11
English Ave.	11	Twenty-second Ave.	11	Naval Station	11
English Ave.	11	Twenty-third Ave.	11	Naval Station	11
English Ave.	11	Twenty-fourth Ave.	11	Naval Station	11
English Ave.	11	Twenty-fifth Ave.	11	Naval Station	11
English Ave.	11	Twenty-sixth Ave.	11	Naval Station	11
English Ave.	11	Twenty-seventh Ave.	11	Naval Station	11
English Ave.	11	Twenty-eighth Ave.	11	Naval Station	11
English Ave.	11	Twenty-ninth Ave.	11	Naval Station	11
English Ave.	11	Thirtieth Ave.	11	Naval Station	11
English Ave.	11	Thirty-first Ave.	11	Naval Station	11
English Ave.	11	Thirty-second Ave.	11	Naval Station	11
English Ave.	11	Thirty-third Ave.	11	Naval Station	11
English Ave.	11	Thirty-fourth Ave.	11	Naval Station	11
English Ave.	11	Thirty-fifth Ave.	11	Naval Station	11
English Ave.	11	Thirty-sixth Ave.	11	Naval Station	11
English Ave.	11	Thirty-seventh Ave.	11	Naval Station	11
English Ave.	11	Thirty-eighth Ave.	11	Naval Station	11
English Ave.	11	Thirty-ninth Ave.	11	Naval Station	11
English Ave.	11	Fortieth Ave.	11	Naval Station	11
English Ave.	11	Forty-first Ave.	11	Naval Station	11
English Ave.	11	Forty-second Ave.	11	Naval Station	11
English Ave.	11	Forty-third Ave.	11	Naval Station	11
English Ave.	11	Forty-fourth Ave.	11	Naval Station	11
English Ave.	11	Forty-fifth Ave.	11	Naval Station	11
English Ave.	11	Forty-sixth Ave.	11	Naval Station	11
English Ave.	11	Forty-seventh Ave.	11	Naval Station	11
English Ave.	11	Forty-eighth Ave.	11	Naval Station	11
English Ave.	11	Forty-ninth Ave.	11	Naval Station	11
English Ave.	11	Fiftieth Ave.	11	Naval Station	11
English Ave.	11	Fifty-first Ave.	11	Naval Station	11
English Ave.	11	Fifty-second Ave.	11	Naval Station	11
English Ave.	11	Fifty-third Ave.	11	Naval Station	11
English Ave.	11	Fifty-fourth Ave.	11	Naval Station	11
English Ave.	11	Fifty-fifth Ave.	11	Naval Station	11
English Ave.	11	Fifty-sixth Ave.	11	Naval Station	11
English Ave.	11	Fifty-seventh Ave.	11	Naval Station	11
English Ave.	11	Fifty-eighth Ave.	11	Naval Station	11
English Ave.	11	Fifty-ninth Ave.	11	Naval Station	11
English Ave.	11	Sixtieth Ave.	11	Naval Station	11
English Ave.	11	Sixty-first Ave.	11	Naval Station	11
English Ave.	11	Sixty-second Ave.	11	Naval Station	11
English Ave.	11	Sixty-third Ave.	11	Naval Station	11
English Ave.	11	Sixty-fourth Ave.	11	Naval Station	11
English Ave.	11	Sixty-fifth Ave.	11	Naval Station	11
English Ave.	11	Sixty-sixth Ave.	11	Naval Station	11
English Ave.	11	Sixty-seventh Ave.	11	Naval Station	11
English Ave.	11	Sixty-eighth Ave.	11	Naval Station	11
English Ave.	11	Sixty-ninth Ave.	11	Naval Station	11
English Ave.	11	Seventieth Ave.	11	Naval Station	11
English Ave.	11	Seventy-first Ave.	11	Naval Station	11


NOTE.—Home Numbers given are arbitrary.



CONTINENTAL REFINING CO.
OIL REFINERY

Stress ist ein Begriff, den wir alle kennen, aber was bedeutet er eigentlich? Stress ist eine Reaktion des Körpers auf eine Belastung. Diese Belastung kann von innen kommen (z.B. Gedanken, Emotionen) oder von außen (z.B. Umwelt, andere Menschen). Stress ist eine natürliche Reaktion, die uns hilft, mit schwierigen Situationen umzugehen. Aber wenn Stress zu lange anhält, kann er zu gesundheitlichen Problemen führen. Es ist wichtig, Stress zu erkennen und zu managen, um ein gesundes Leben zu führen.

Located 1/2 Mile N. of P.O.
on EXPOSURE HWY. 50E



398F-439D-A25F

Certification #



Enclosure 2b: Aerial photographs

North Tank Farm

Loading Dock

Lorraine
process area

Wilcox process
area

East Tank Farm

Site in Sec 20&29-16N-9E
Creek County
1"= 660' 8/19/1941

0 330 660 Feet
August 21, 2015

Wilcox Oil Company Superfund Site and National Historic Preservation Act Section 106
Boundaries are approximate.

Page 18 of 62

North Tank Farm

Loading Dock


Lorraine
process area

Wilcox process
area

East Tank Farm

Site in Sec 20&29-16N-9E
Creek County
1"= 660' 7/8/1956
0 330 660 Feet
Wilcox Oil Company Superfund Site and National Historic Preservation Act Section 106
August 21, 2015

Boundaries are approximate.



North Tank Farm

Loading Dock


Lorraine
process area

Wilcox process
area

East Tank Farm

Site in Sec 20&29-16N-9E
Creek County
1"= 660' 12/14/1969
0 330 660 Feet
Wilcox Oil Company Superfund Site and National Historic Preservation Act Section 106
August 21, 2015

Boundaries are approximate.



North Tank Farm

Loading Dock

Lorraine
process area

Wilcox process
area

East Tank Farm

Site in Sec 20&29-16N-9E
Creek County
1"= 660' 2/27/1972
0 330 660 Feet
Wilcox Oil Company Superfund Site and National Historic Preservation Act Section 106
August 21, 2015

Boundaries are approximate.

North Tank Farm

Loading Dock

Lorraine
process area


Wilcox process
area

East Tank Farm

Site in Sec 20&29-16N-9E
Creek County
1"= 660' 11/5/1979
0 330 660
Wilcox Oil Company Superfund Site and National Historic Preservation Act Section 106
August 21, 2015
Feet

Boundaries are approximate.

Wilcox Oil Company 1995 Aerial Photograph



North Tank Farm

Loading Dock

Lorraine
process
area

Wilcox process
area

East Tank Farm

Google earth

Wilcox Oil Company Superfund Site and National Historic Preservation Act Section 106


Image U.S. Geological Survey 2015

Boundaries are approximate.

Page 23 of 62
1000 ft



Wilcox Oil Company 2003 Aerial Photograph



Google earth

Wilcox Oil Company Superfund Site and National Historic Preservation Act Section 106


Image USDA Farm Service Agency

Page 24 of 62

1000 ft

Boundaries are approximate.

Wilcox Oil Company 2004 Aerial Photograph



Google earth

Wilcox Oil Company Superfund Site and National Historic Preservation Act Section 106

Image © 2015 DigitalGlobe, 2015


Page 25 of 62

1000 ft



Boundaries are approximate.

Wilcox Oil Company 2005 Aerial Photograph



Google earth

Wilcox Oil Company Superfund Site and National Historic Preservation Act Section 106


Image USDA Farm Service Agency

Page 26 of 62

1000 ft

Boundaries are approximate.

Wilcox Oil Company 2006 Aerial Photograph



North Tank Farm

Loading Dock

Lorraine
process
area

Wilcox process
area

East Tank Farm

Google earth

Wilcox Oil Company Superfund Site and National Historic Preservation Act Section 106

Image USDA Farm Service Agency

Boundaries are approximate.

Page 27 of 62

1000 ft



Wilcox Oil Company 2008 Aerial Photograph

North Tank Farm

Loading Dock

Lorraine
process
area

Wilcox process
area

East Tank Farm

Google earth

Wilcox Oil Company Superfund Site and National Historic Preservation Act Section 106

Image USDA Farm Service Agency


Boundaries are approximate.

Page 28 of 62

1000 ft



Wilcox Oil Company 2010 Aerial Photograph



North Tank Farm

Loading Dock

Lorraine
process
area

Wilcox process
area

East Tank Farm

Google earth

Wilcox Oil Company Superfund Site and National Historic Preservation Act Section 106


Image USDA Farm Service Agency

Page 29 of 62

1000 ft

Boundaries are approximate.

Wilcox Oil Company 2012 Aerial Photograph



North Tank Farm

Loading Dock

Lorraine
process
area

Wilcox process
area

East Tank Farm



Wilcox Oil Company 2014 Aerial Photograph

North Tank Farm

Loading Dock

Lorraine
process
area

Wilcox process
area

East Tank Farm

Google Earth

Wilcox Oil Company Superfund Site and National Historic Preservation Act Section 106
August 31, 2015

Page 31 of 62
1000 ft



Boundaries are approximate.

Enclosure 2c: Site photographs



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 6

SUPERFUND DIVISION

1445 Ross Avenue, Suite 1200

Dallas, Texas 75202-2733

MEMORANDUM

To: File

Todd Downham
ODEQ Project Manager

From: Katrina Higgins-Coltrain
EPA Remedial Project Manager

Subject: March 24, 2015, Wilcox Oil Company Superfund Site Tour Summary

On March 24, 2015, the Oklahoma Department of Environmental Quality (ODEQ) and the Environmental Protection Agency (EPA) met at the Wilcox Oil Company Superfund Site to tour the site and meet with residents. The purpose of the visit was to better understand the potential distribution of contamination, determine the need for site fencing and signage, and ask nearby residents if they would be interested in having their yards tested.

Below are photographs taken during the site tour and a reference map. Two residents supported having their yards tested and signed consent forms. Four other residents were interested and accepted the consent form for review and discussion prior to signing. Three residents were not home, and follow-up discussions are planned. One of these is known to have small children. Three residents have moved out of homes. Two on the site and one across the street. One moved due to site conditions. Based on conversations with neighbors, the other two residents moved due to matters unrelated to site conditions. The residents were provided a brief discussion of the sampling, the Superfund Process map, fact sheets on the site, and fact sheets related to the contaminants lead, total petroleum hydrocarbons, and polycyclic aromatic hydrocarbons.

Site Participants included Todd Downham (ODEQ), Katrina Higgins-Coltrain (EPA), and Mark Hayes (EPA). We met with [REDACTED] (church), [REDACTED] (church), [REDACTED] (consultant to the church), [REDACTED] (resident), [REDACTED] (resident), [REDACTED] (resident), [REDACTED] (resident), and one additional resident name not recorded.



Picture 1 – Property 10: Waste material at surface. Northwest side of property on the upper bank of Sand Creek.



Picture 2 – Property 10: Waste material at surface. West side of property on the upper bank of Sand Creek.



Picture 3 – Property 10: Waste material at surface. Southwest side of property.



Picture 4 – Property 10: Waste material at surface. Southwest side of property on the upper bank of Sand Creek within the utility right-of-way. Utilities work on the poles resulted in waste discovery.



Picture 5 – Property 10: Waste material at surface. Southwest side of property on the upper bank of Sand Creek within the utility right-of-way. Utilities work on the poles resulted in waste discovery.



Picture 6 – Property 10: East Bank of Sand Creek along the northwest of the property. Iron staining and Iron sheen. No visible seep; however, resident has seen an oil substance seep in this area.



Picture 7 – Property 10: East Bank of Sand Creek. No visible seep; however, resident has seen an oil substance seep in this area. Iron staining and Iron sheen.



Picture 8 – Property 10: The steep banks of Sand Creek viewing south.



Picture 9 – Property 10: Sand Creek culvert under the railroad tracks on the south end of the property.



Picture 10 – Property 8: Process Area building remnant.



Picture 11 – Property 8: Process Area building remnant.



Picture 12 – Property 8: Process Area Tank.



Picture 13 – Property 8: Process Area trash and accumulated items.



Picture 14 – Property 8: Process Area building remnant. Underground ‘sumps’ with connecting tunnels.



Picture 15 – Property 8: Process Area building remnant.



Picture 16 – Property 8: Process Area building remnant.



Picture 17 – Property 8: Process Area building remnant.



Picture 18 – Property 8: Waste material at surface.



Picture 19 – Property 8: Process Area building remnant.



Picture 20 – Property 8: Process Area building remnant.



Picture 21 – Property 8: Waste material at surface.



Picture 22 – Property 8: Process Area building remnant.



Picture 23 – Property 8: Process Area Tank.



Picture 24 – Property 8: Process Area ‘foundation’ pond. This is a concrete form that is filled with water. No idea on depth.



Picture 25 – Property 8: Process Area ‘foundation’ pond. This is a concrete form that is filled with water. No idea on depth.



Picture 26 – Property 8: Process Area building remnant.



Picture 27 – Property 8: Process Area building remnant.



Picture 28 – Property 8: Process Area soil. Area of no vegetation and potentially the location of historic acid/caustic tanks.



Picture 29 – Property 8: Pond in the Process Area on adjacent Property 11.



Picture 30 – Property 8: Process Area waste at surface.



Picture 31 – Property 8: Process Area building remnant.



Picture 32 – Property 8: Process Area tank.



Picture 33 – Property 8: Process Area tank.



Picture 34 – Property 8: Process Area ‘sump’.



Picture 35 – Property 8: Process Area ‘sump’.



Picture 36 – Property 8: Process Area rail car. This car was labeled *Enjay*, a division of *Humble Oil Refining*, UTLX 83010, Union Tank Car Company.



Picture 37 – Property 8: Process Area building remnant.



Picture 38 – Property 8: Process Area building remnant.



Picture 39 – Property 8: Process Area building remnant.



Picture 40 – Property 8: Process Area potential waste at surface.



Picture 41 – Property 8: Process Area tank.



Picture 42 – Property 8: Process Area tanks.



Picture 43 – Property 7: Waste Material at surface.



Picture 44 – Property 7: Waste Material at surface.



Picture 45 – Property 7: Waste Material at surface.



Picture 46 – Property 7: Waste Material at surface.



Picture 47 – Property 7: Pond located in the southwest corner.




Figure 1: Reference figure for cited properties.

Enclosure 3: Summary description of the effort we made to identify historic properties

In an effort to identify historic properties within the project area letters were sent to the Oklahoma Historical Society (July 14, 2015) and the Oklahoma Archeological Survey (July 14, 2015) to assist in identification of historical locations/properties in the area. In addition, the Oklahoma online registries were searched. In response on July 27, 2015, the Oklahoma Archeological Survey did not identify archaeological sites within our project area; however, the letter indicated that archeological material are likely to be encountered. In response on July 29, 2015, the Oklahoma Historical Society indicated that a determination could not be made at this time due to insufficient information.

Oklahoma Listings in the National Register of Historic Places

The following districts, buildings, sites, structures, and objects are listed in the National Register of Historic Places as of July 10, 2015. Each entry includes: property name (followed in parentheses by archaeological site number and/or name of MPS, MRA or TR nomination, if any of these designations are applicable); location (unless this information is restricted); date of listing; National Register Criteria Code(s) under which the property was listed; any appropriate HABS, HAER and/or NHL designations; and the National Register Information System (NRIS) assigned number; and if the property has been removed from the National Register, that information will be noted in parentheses.

Creek County (Code 037)

Please refer to the National Registry Map for locations.

Bristow:

1. Beard Motor Company
[Route 66 & Associated Historic Resources in Oklahoma MPS], 210 East 9th, 5/27/04, A,C, 04000522.
2. Bristow Firestone Service Station
[Route 66 & Associated Historic Resources in Oklahoma MPS], 321 North Main, 9/6/07, A,C, 07000912.
3. Bristow Motor Company Building
[Route 66 & Associated Historic Resources in Oklahoma MPS], 500 North Main, 2/23/95, A, 95000032.
4. Bristow Presbyterian Church
6th & Elm, 10/3/79, C,a, 79001992.
5. Bristow Tire Shop
[Route 66 & Associated Historic Resources in Oklahoma MPS], 115 West 4th, 2/23/95, A,C, 95000033.
6. Texaco Service Station
[Route 66 & Associated Historic Resources in Oklahoma MPS], 201 West 4th, 2/23/95, A,C, 95000034.


Bristow vicinity:

7. Little Deep Fork Creek Bridge
[Route 66 & Associated Historic Resources in Oklahoma MPS], .33 mile East of Jct. of County Roads #E0830 & #N3700, 12/5/03, A,C, 03001237.
8. Tank Farm Loop Route 66 Roadbed
[Route 66 & Associated Historic Resources in Oklahoma MPS], Jct. of SH-66 & Old Highway 66, .6 mile West of I-44 Overpass, 9/6/06, A,C, 06000797.

Following is a guide to the codes used in the entries.

- A,B,C, or D: Listed in the National Register for Criterion A, association with important events; B, association with important persons; C, architectural, artistic, or design merit, or representative of a period or a type of construction; or D, likely to yield information.
- a - g: Property types eligible for the National Register only under special circumstances: (a) religious property; (b) moved property; (c) birthplace or grave; (d) cemetery; (e) reconstructed property; (f) commemorative property; or (g) property less than fifty (50) years old when listed.
- AD: Additional Documentation.
- HABS: Documented by the Historic American Buildings Survey.
- HAER: Documented by the Historic American Engineering Record.
- MPS: Individually listed as part of a Multiple Property Submission.
- MRA: Individually listed as part of a Multiple Resource Area nomination.
- NHL: Designated a National Historic Landmark.
- TR: Individually listed as part of a Thematic Resource nomination.

Reference: National Register Handbook. State Historic Preservation Office, Oklahoma Historical Society. (<http://www.okhistory.org/shpo/NRHANDBK.htm>). July 10, 2015.



- Historic Locations
- Approximate Project Boundary
- 1 number representing historic location



1. Beard Motor Company
2. Bristow Firestone Service Station
3. Bristow Motor Company Building
4. Bristow Presbyterian Church
5. Bristow Tire Shop
6. Texaco Service Station
7. Little Deep Fork Creek Bridge
8. Tank Farm Loop Route 66 Roadbed

Enclosure 4: Basis for determining that no historic properties are present or affected

Based on our review of the National Register of Historic Places, the history of operation, and investigations performed by ODEQ, no State cultural or historical resources or properties are located within the project boundary or will be affected by the investigation and potential remediation that will be conducted by EPA and the ODEQ.

1. Review of the National Register of Historic Places, did not identify any resources or landmarks located within the project boundaries.
2. The Site property was the location of an active oil refinery from approximately 1915 to 1963.
3. Aerial photographs of the Site show refinery operations extended across the entire Site. When operations ceased, most of the refinery buildings, tanks, piping, and infrastructure were dismantled, demolished, and left for ruin. The only activity conducted was the sale and construction of single family homes and a church. The church and the homes exists today.
4. Site photographs show the location of refinery waste material throughout the Site property. The location of the waste material coincides, in many cases, with the locations of the process area and individual tank locations in the tank farm areas.
5. Investigations conducted by ODEQ show waste to be present. High concentrations of organics and metals have been found in soil, sediment, and surface water. Ground water is expected to be impacted due to the presence of a light non-aqueous phase liquid (i.e., a liquid that does not dissolve in water and floats on the water's surface) near the church. The exact size and extent is currently unknown.

As part of the investigation, Site field studies including subsurface testing, will be conducted. Should new information becomes available that would indicate the presence of cultural or historical resources, we will coordinate with your office on any future actions.